

# Oil Field Environmental Incident Summary

**Incident:** 20150108145706      **Date/Time of Notice:** 01/08/2015 14:57

**Responsible Party:** ONEOK Rockies Midstream

**Well Operator:**

**Well Name:** Marmarth Plant

**Field Name:**

**Well File #:**

**Date Incident:** 1/5/2015      **Time Incident:** 12:00

**Facility ID Number:**

**County:** SLOPE

**Twp:** 136

**Rng:** 106

**Sec:** 36

**Qtr:**

**Location Description:** 77-06 172 Avenue  
Marmarth, ND 58643

**Submitted By:** Jason Lyons

**Received By:**

**Contact Person:** Jason Lyons  
2700 Lincoln Ave  
Sidney, MT 59270

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	5	Gallons	5	Gallons		

**Description of Other Released Contaminant:**

Approximately 5 gallons of Therminol 55.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

There were no offsite impacts or immediate risks to human health or the environment.

**Areal Extent:**

Approximately 10 feet X 10 feet

**Potential Environmental Impacts:**

There were no impacts to surface water or groundwater.

**Action Taken or Planned:**

Released material was recovered with absorbent and containerized. Material residue is suspended in a frozen state on the facility's ground surface. The remaining clean-up action will take place as soon as weather permits.

**Wastes Disposal Location:** Recovered wastes will be disposed in accordance with applicable State/Federal regulations.

**Agencies Involved:****Updates**

---

**Date:** 1/9/2015      **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill occurred at a site not associated with exploration or production. Followup is necessary.

---

**Date:** 2/4/2015      **Status:** Inspection

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release remained on site with no environmental risk. Release has been cleaned up.